

#### LEGEND

- Found BLM aluminum cap
- ⊕ Set 3.25" aluminum cap monument stamped "LS 34979"
- Set rebar with plastic cap stamped "LS 34979"

#### NOTES:

1. No evidence of original corners of the Highland Chief Millsite was found by this survey. Corner Nos. 1 and 2 fall in slide rock, and Corner Nos. 3 and 4 fall on the westerly and easterly edges of an avalanche chute.
2. Property located by field measurements to found BLM monuments at Corners 3 and 4 of the Sunshine No. 1 Lode, M.S. 17467, using record tie between said Corner No. 3 and Corner No. 4 of the Highland Chief Millsite, M.S. 1209B, as shown on original survey plat of said Sunshine Lode. Using these BLM monuments to control the location of the Highland Chief Millsite place said millsite in a harmonious relationship with a tunnel, a tie to which is shown on the plat and described in the notes of the original survey of said Millsite.
3. Basis of bearings is N 83°50' E between said Corners No. 3 and 4 of said Sunshine Lode.
4. Original stone monument was found at Corner No. 4 of the Calcite Lode, M.S. 20166. Said stone was found lying loose in slide rock. Original plat and notes of said M.S. 20166 show a tie to Corner No. 2 of the Highland Chief Millsite. Using this stone to control the location of the Highland Chief Millsite would not place said Millsite in a harmonious location relative to tunnel as shown on plat of said Millsite, therefore said stone was not used as control for this survey.